

Volvo FMX 460 6x4 / Euro 6 / Chassis / Damaged Cabine

General features

Brand	Volvo
Model	FMX 460
Subcategory	Chassis cab
Odometer reading	228.930km
Construction year	2020
Date of first registration	12-11-2020
Condition	Used
Fuel	Diesel
Emission class	Euro 6



Characteristics

GVW

26.000kg

Volvo FMX 460 6x4 / Euro 6 / Chassis / Damaged Cabine

Technical specifications

Number of axes	3
Axis configuration	6x4
Transmission	Automatic
Engine output	345kw

Description

Volvo FMX 460 Chassis Cabine Traction 6x4 Automatic gearbox Euro 6 engine (460ps) Drawbar coupling Damaged cabine Belgium registration !!

Accessories

- 2 pedal control
- Trailer coupling
- Airbags
- Automatic
- Cabin
- Central doorlocking
- Electric windows
- Closed cabin
- Air suspension system
- Air Suspension Seats
- Passenger seat
- Rain Sensor
- Heated Mirrors
- Power steering
- Spotlight rear
- Spotlight front
- Heater
- Front window
- Anti-lock braking system
- Air conditioning
- Leaf spring suspension
- Central locking
- Cruise control
- Electrically operated windows
- Toolbox
- Air horn
- Air suspension
- Fog lights
- Parabolic suspension
- PTO

- Radio/CD player
- Particulate filter
- Coupling
- Heavy duty engine brake
- Spotlights
- Side door
- Visor
- Electrically adjustable door mirrors